Spot the Hazard.

Can you spot the hazards?



Image 1111: Cement Masons/Washington State Department of Labor and Industries http://www.elcosh.org



- Missing rungs
 - Broken rails
- Hazards

 Unsafe job-made ladder