Spot the Hazard.

Can you spot the hazards?



Image 226: NIOSH/John Rekus http://www.elcosh.org

Ladder used is the top of an extent ion ladder, does not have feet

Improper ladder use (less than 3 feet above the point of support, not secured)

Look ponsekeeping

Scaffold footing not properly braced

Scattold set up on top of unsecured excavation (no caution tape)

Scaffold missing: cross bracing, full planking, falling object protection

Hazards

